

# SRX LP

LANDFILL PUMP

“Simply”  
**Reliable**



# SRX LP Landfill Pump



**The SRX LP Pump was removed from the well for inspection and cleaning after five months of trouble free operation.**

---

# SRX LP Landfill Pump

Minimal build-up has occurred around the air valve and pump linkage. This is attributed to the positive air valve seal



# SRX LP Landfill Pump

Minimal build-up occurred on the center discharge tube. This is primarily due to the polished OD of the discharge tube and the movement of the hard surface Ebonite Float



# SRX LP Landfill Pump



**Build-up on the float OD and at the bottom of the arch assembly. The hard/slick surface of the float allowed the build-up to be wiped away with a light solvent and shop cloths**



# SRX LP Landfill Pump



**The Pump was completely disassembled - cleaned and reassembled in the field. Since the float and control rod are easily removed cleaning was accomplished by wiping the pump with shop cloths and a light solvent in less then 30 minutes**

**SRX LP**

**SIMPLY RELIABLE**

Any questions?